DIR-826L Firmware Release Notes

Firmware: FW v1.02
Hardware: Rev.Ax
Date: 2012/10/06

Problems Resolved:

Enhancements:

Adding storage wizard.

Enhance setup wizard for wireless client.

Enhance Wireless performance.

Enhance USB throughput.

Enhance PPTP/L2TP throughput

Enhance IPv6 auto-detection.

Enhance varies IPv6 connection mode.

Storage function is now enabled by default.

Know Issues:

When downgrading to firmware version 1.01 or older, the device may hang during the boot up process after the downgrade is completed. If you encounter this problem, press the hardware reset button for five seconds and restart the device.

--------------------- END ---------------------