The new image file (*.con) is encrypted which starting from v6.30.016. It needs upgrading tof/wv6.30.16(.hex)first if attempting to upgrade from (v6.20 or older) to v6.30(.con).

Use v6.30.016backup encrypted firmware file (.con) to upgrade firmware size will change to 12775084B, normal v6.30.016hex file upgrade firmware size is 12774896B.